

Fastness

	Light	Perspiration			Drycleaning			Migration PVC	Penetration	Metal	Solubility g/l 60°C
		N	WO	CO	N	WO	CO				
YELLOW GS	4	3	2	4	4	3	4	3	3		50
YELLOW NM	4-5	3	4	3	3	4	4	4	3	+	50
YELLOW SR	3-4	3	3	2	3	4	4	4	3-4	+	50
YELLOW MS	3-4	3	3	3	2	3	4	4	4-5		40
ORANGE CA	4-5	2	3	3	3	4	4	4	3		60
ORANGE II	3	2	2	2	2	3	3	3	4		50
RED R	2-3	1	2	3	2	3	4	3	3		30
RED GR	3-4	2	3	3	3-4	4	4	3-4	3-4		30
RED NG	2-3	3	4	2	2	3	3	2-3	3-4		40
RED SBA	3	3	3	3	3-4	3-4	4	3-4	2		40
RED 2B	2-3	3-4	3	3-4	3	4	5	3-4	3		40



ALPINE ELEGANCE
DYESTUFF



Fastness											
	Light	Perspiration			Drycleaning			Migration PVC	Penetration	Metal	Solubility g/l
		N	WO	CO	N	WO	CO				
											60°C
FUSCHIA RL	3	3	4	3-4	2-3	4-5	4	3	3-4		50
BORDEAUX BS	3	2	3	3	2	3	3	2-3	3		20
BORDEAUX V	3-4	3-4	3-4	2	3	2	3	3	4	+	30
BORDEAUX FR	3-4	3	2-3	1-2	3	4	4	3-4	3		30
VIOLET LN	3	2-3	2	2	2	3	4	2-3	3		50
BLUE NL	3-4	3-4	3	2-3	3	4	4	3-4	3		40
BLUE N	4	3-4	4	4	4	5	3	3-4	3		50
BLUE NB	4	4	3	3	3	5	4	4	3-4	+	30
BLUE JN	4	3	2-3	2-3	3-4	4	5	4	3	+	40
TURQUOISE LB	3-4	3	3	3	3	3	4	3	3-4		50
GREEN NB	4-5	3-4	2-3	2	3	4	3	3-4	4		50


 ALPINE ELEGANCE
 DYESTUFF



Fastness											
	Light	Perspiration			Drycleaning			Migration PVC	Penetration	Metal	Solubility g/l
		N	WO	CO	N	WO	CO				
											60°C
DARK GREEN 2N	3-4	2	3	3	3	4	4	4	4-5		45
OLIVE BROWN 2N	4	3	4	3	3	5	4	4	4	+	35
OLIVE OS	3-4	3	3	4	3	4	4	3-4	3-4	+	70
DARK OLIVE MB	4	2-3	3	4	2-3	4	4	4	4-5	+	50
BEIGE L	3-4	3	4	4	4	5	4	4-5	3-4	+	60
BEIGE N	3-4	3	4	4	3	4	4	3-4	3-4	+	60
BEIGE YK	3-4	3	4	4	3	3	4	3-4	4		50
YELLOW BROWN 2 NGB	3	3	4	4	4	5	5	4	3-4		60
HAVANA N 3G	2-3	3	4	4	2	3	4	3	3		45
BROWN 2 NG	3-4	3	4	4	2-3	4	4	3-4	4-5		35
BROWN SG	3-4	3	4	4	4	5	4	3-4	4	+	60


 ALPINE ELEGANCE
 DYESTUFF



Fastness											
	Light	Perspiration			Drycleaning			Migration PVC	Penetration	Metal	Solubility g/l 60°C
		N	WO	CO	N	WO	CO				
BROWN G CONZ	3-4	3	4	4	4	5	4	4-5	4	+	75
ORANGE BROWN KD	4	3	2	3	3-4	4	3	4-5	4-5	+	45
BROWN 2 MFR	3-4	2	3	3	3-4	4	4	3-4	3-4	+	45
BROWN RT	4	3-4	4	4	3-4	4-5	4-5	4	4	+	50
BROWN DR	3-4	3	3	3	3	4	4	3-4	3-4	+	50
YELLOW BROWN EK	4	3	3-4	4	3	4	4	4	3-4	+	40
BROWN NGT	4	3	4	4	3	4	5	3-4	3-4	+	60
BROWN 2 NT	2-3	3-4	3	4	4	4-5	3-4	2-3	4	+	30
BROWN YB	4	3	3-4	3-4	3	3-4	3-4	4	4	+	30
BROWN RB	4	3	3-4	3-4	3	3-4	3-4	4	4	+	30
BROWN CN	3-4	3	2	2	4	3	2	3	3-4		30


ALPINE ELEGANCE
 DYESTUFF



Fastness

	Light	Perspiration			Drycleaning			Migration PVC	Penetration	Metal	Solubility g/l 60°C
		N	WO	CO	N	WO	CO				
BROWN 2 RL	3-4	3-4	3-4	3	3-4	4	4	4	2-3	+	40
DARK BROWN EM	3-4	4	3	2	3-4	4-5	4	3-4	3-4		45
FERRO BROWN R	2-3	3	4	4	3	4	4	3-4	3		60
BROWN 2 NR	2-3	3-4	3	2	3-4	4-5	3-4	2-3	3		30
RED BROWN S	3-4	2-3	3	3	3-4	4-5	4-5	3-4	3		50
BROWN DZ	3-4	3-4	2-3	2	3-4	4	4	4	3		50
DARK BROWN LG	5	3-4	2	2	3	3	2	2-3	3-4	+	50
BROWN D	4-5	3	2	3	3	3	3	3-4	3		50
BROWN B	4-5	3	2-3	3	3	3	3	3	3-4	+	40
BROWN DR-MC	4	3-4	3-4	3	3	3	3	3	2-3	+	50
BROWN DB	2-3	3-4	3	2	3-4	4-5	3-4	2-3	3		35



Fastness											
	Light	Perspiration			Drycleaning			Migration PVC	Penetration	Metal	Solubility g/l
		N	WO	CO	N	WO	CO				
		N	WO	CO	N	WO	CO				60°C
GREY 2 GB	4	3-4	2	2	2-3	5	5	3-4	3-4	+	50
GREY 2 GC	4	3	3	4	2-3	4	4	4-5	3	+	40
BLACK 400 R	3-4	3-4	3	3	3-4	4	4	4-5	4		50
BLACK RGR KONZ	3-4	3-4	3	3	3-4	4	4	4-5	4		50
TOP BLACK A	3-4	3-4	3	3	3-4	3	4	4-5	4		50
TOP BLACK AR	3-4	3-4	3-4	3-4	3-4	4	4	4-5	3-4		60
TOP BLACK BLN	3-4	4	2	2	3	2-3	3-4	4	3-4	+	60
TOP BLACK MC	5	3	3	2-3	3	4	4	4	3	+	70


 ALPINE ELEGANCE
 DYESTUFF

